

BIT Šroubovací nástavec



| Katalogové číslo | Popis | Délka mm L | Balení |
|------------------|-------|---------------|--------|
| 4001006 | PZ2 | 25 | 25 |
| 4001056 | PZ2 | 50 | 10 |
| 4001106 | PZ2 | 70 | 5 |
| 4001007 | PZ3 | 25 | 25 |
| 4001057 | PZ3 | 50 | 10 |
| 4001107 | PZ3 | 70 | 5 |

BIT Šroubovací nástavec Pozidrive

| Katalogové číslo | Popis | Délka mm L | Balení |
|------------------|-------|---------------|--------|
| 4001002 | PH2 | 25 | 25 |
| 4001052 | PH2 | 50 | 10 |
| 4001102 | PH2 | 70 | 5 |
| 4001004 | PH4 | 25 | 25 |

BIT Šroubovací nástavec Phillips

| Katalogové číslo | Popis | Délka mm L | Balení |
|------------------|-------|---------------|--------|
| 4001133 | T15 | 70 | 5 |
| 4001034 | T20 | 25 | 25 |
| 4001044 | T20 | 50 | 10 |
| 4001134 | T20 | 70 | 5 |
| 4001035 | T25 | 25 | 25 |
| 4001045 | T25 | 50 | 10 |
| 4001135 | T25 | 70 | 5 |
| 4001037 | T30 | 25 | 25 |
| 4001047 | T30 | 50 | 10 |
| 4001137 | T30 | 70 | 5 |
| 4001038 | T40 | 25 | 25 |
| 4001048 | T40 | 50 | 10 |
| 4001138 | T40 | 70 | 5 |

BIT Šroubovací nástavec T15 -T40

| Katalogové číslo | Popis | Balení |
|------------------|---------------------|--------|
| 4001013 | Adaptér 1/4" / 1/4" | 1 |

MMH Magnetický držák

| Katalogové číslo | Popis | Balení |
|------------------|-----------------------|--------|
| 4001016 | Adaptér SDS-Plus 1/4" | 1 |

MMH Magnetický držák

| Katalogové číslo | Popis | Počet kusů v setu | Balení |
|------------------|--|-------------------|--------|
| 4001900 | Ph1-3, Pz1-3, T10-40, Hex3-5, SL4.5-6.5, Fox1/4" | 19 | 1 |

BIT-SET Set, 19-ti dílný